

QUALITY REMARK: AEPD
QUALITY REQUIREMENT NUMBER 441
MRB REPAIR

TYPE 11: REPAIR PROCEDURE FOR B50TF119 CLASS A COMBINED WITH
F50TF19 CLASS A FOR MICROSTRUCTURE AND THICKNESS ONLY.

SUPPLIER TO SUBMIT THE FOLLOWING TO PURCHASER IN
SHIPPING CONTAINER WITH PARTS PLUS DUPLICATE COPIES
UNDER SEPARATE MAILING TO APPROPRIATE GE CONTRACT ADMINISTRATOR:

CERTIFICATE OF CONFORMANCE TO MRB REPAIR
AND ALL APPLICABLE SPECIFICATIONS REFERENCED
ON MRB REPAIR PROCEDURE AND PURCHASE ORDER.
SAID CERTIFICATE SHALL INCLUDE DOCUMENTATION THAT
PARTS WERE VISUALLY INSPECTED AND ACCEPTED BEFORE AND
AFTER SPRAY FOR CHIPPING, FLAKING, CRACKING,
OVERSPRAY, AND OTHER VISUAL DEFECTS.

DOCUMENTATION OF INSPECTION OF QUALITY AND AMOUNT OF SPRAY PER F50TF18
CLASS A FOR MICROSTRUCTURE AND THICKNESS COMPLIANCE ONLY.

COPY OF MRB REPAIR PROCEDURE WITH SUPPLIER
QUALITY INSPECTOR OR REPRESENTATIVE SIGNATURE
SIGN-OFF OR STAMP ON ALL APPLICABLE ITEMS
ON MRB REPAIR PROCEDURE INDICATING COMPLETION
OF AND COMPLIANCE TO ALL REQUIREMENTS.