

QUALITY: GESS
REQUIREMENT G42

IDENTIFICATION OF UNQUALIFIED GROUND SUPPORT EQUIPMENT

THE SUPPLIER WILL IDENTIFY THE OVERPACK FOR UNQUALIFIED GROUND SUPPORT EQUIPMENT TO BE SHIPPED TO GE SUPPORT SERVICES AS FOLLOWS:

THE IDENTIFICATION MUST BE IN RED INK OR PAINT, STENCILLED OR PRINTED WITH THE WORDS "UNQUALIFIED GSE"

THE LOCATION OF THE MARKING IS TO BE VISIBLE AND EASILY IDENTIFIED.
THE IDENTIFICATION MAY BE IN MORE THAN ONE LOCATION.