

Technical Manual Index

CJ610 TURBOJET and CF700 TURBOFAN

Component Maintenance Manual
September 1, 2023

The manuals are listed in ATA number order. The Rev. Cycle column indicates the following planned revision frequency for each publication listed:

90 - - - - - 90 day revision cycle (Quarterly updates)
180 - - - - - 180 day revision cycle (Semi-annual updates)
365 - - - - - 365 day revision cycle (Annual updates)
AR - - - - - As Required revision cycle

<u>ATA Number</u>	<u>Publ. Number</u>	<u>Engine Model</u>	<u>Nomenclature</u>	<u>Part Number</u>	<u>VIN</u>	<u>OEM Name (Vendor Code)</u>	<u>Basic Issue Date</u>	<u>Rev. No.</u>	<u>Rev. Date</u>	<u>Rev. Cycle</u>
73-11-0	SEI-154	ALL	Fuel Pump	37E501242P109 37E501242P110 37E501242P113	9234-A7 9234-A8 9234-A9	Chandler Evans (11599)	1/31/67	21	5/31/98	AR
73-12-0	SEI-154	CJ610-1/ -5/-9	Fuel Filter	37C311075P103	AC4806-45	Aircraft Porous Media (01414)	1/31/67	20	12/31/95	AR
73-13-0	SEI-154	CJ610-1/ -5/-9	Fuel Pressurizing Valve	37C301819G001	-	GE Aircraft Engines (99207)	1/31/67	20	12/31/95	AR
73-14-0	SEI-154	CJ610-1/ -5/-9	Fuel Drain Valve	37C301777G004	-	GE Aircraft Engines (99207)	1/31/67	23	8/15/00	AR
73-15-0	SEI-154	CJ610-4/ -6/-8/-8A	Fuel Pressurizing and Drain Valve	3006T88G01	-	GE Aircraft Engines (99207)	1/31/67	21	5/31/98	AR
73-16-1	SEI-154	ALL	Fuel Nozzle Assembly	37D401657P109 37D401657P110 37D401657P115	5232601 5232890 47728	GMC, Diesel Equipment Div. (71934)	1/31/67	20	12/31/95	AR
73-20-1	SEI-154	ALL	Fuel Control	5001T39 series 5002T94 series	-	GE Aircraft Engines (99207)	1/31/67	22	8/15/99	AR

Technical Manual Index

CJ610 TURBOJET and CF700 TURBOFAN

Component Maintenance Manual September 1, 2023

<u>ATA Number</u>	<u>Publ. Number</u>	<u>Engine Model</u>	<u>Nomenclature</u>	<u>Part Number</u>	<u>VIN</u>	<u>OEM Name (Vendor Code)</u>	<u>Basic Issue Date</u>	<u>Rev. No.</u>	<u>Rev. Date</u>	<u>Rev. Cycle</u>
73-21-0	SEI-154	CJ610-1/-4/ -5/-6/-9 CF700-2C/ -2D/-2D-2	Overspeed Governor Assembly	5006T22P02	8005-004	Woodward Governor (66503)	1/31/67	23	8/15/00	AR
73-21-1	SEI-154	ALL	Overspeed Governor Assembly	5006T14P02 5006T14P04 5012T72P01 5012T73P01	8005-008 8005-016 8005-005 8005-006	Woodward Governor (66503)	1/31/67	23	8/15/00	AR
75-10-0	SEI-154	ALL	Anti-icing Valve	37D401642P103 37D401642P104	123945-2 320765	Whittaker Corp. (79318)	1/31/67	21	5/31/98	AR
75-30-0	SEI-154	CJ610-1/ -4/-6 CF700-2C	Actuator and Arm Assembly	37E501459P101 37E501459P103	7251P101 7251P103	Arkwin Industries (98391)	1/31/67	20	12/31/95	AR
75-30-1	SEI-154	ALL	Actuator and Arm Assembly	5002T48P02	7257-3P02	Arkwin Industries (98391)	1/31/67	22	8/15/99	AR
75-31-1	SEI-154	ALL	Bleed Valve	37E501502P110 37E501502P113	378G3 378-G10	Lytron Inc. (11245)	1/31/67	20	12/31/95	AR
75-32-0	SEI-154	CJ610-4	Feedback Control Assembly	5000T47P01 5000T47P03	17221	Teleflex Inc. (78710)	1/31/67	15	5/1/77	AR

Technical Manual Index

CJ610 TURBOJET and CF700 TURBOFAN

Component Maintenance Manual September 1, 2023

<u>ATA Number</u>	<u>Publ. Number</u>	<u>Engine Model</u>	<u>Nomenclature</u>	<u>Part Number</u>	<u>VIN</u>	<u>OEM Name (Vendor Code)</u>	<u>Basic Issue Date</u>	<u>Rev. No.</u>	<u>Rev. Date</u>	<u>Rev. Cycle</u>
75-32-1	SEI-154	CJ610-1/-5/-9 CF700-2C/-2D/-2D-2	Feedback Control Assembly	6003T46P01	22614	Teleflex Inc. (78710)	1/31/67	15	5/1/77	AR
75-32-2	SEI-154	CJ610-4/-6/-8/-8A	Feedback Control Assembly	5003T58P01	22601	Teleflex Inc. (78710)	1/31/67	15	5/1/77	AR
75-33-0	SEI-154	ALL	Synchronizing Cable Assembly and Adjusting Link	4006T61P01	22722	Teleflex Inc. (78710)	1/31/67	14	4/1/76	AR
77-11-0	SEI-154	CJ610-1/-4/-5/-6/-8/-8A/-9	Exhaust Pressure Probe	37D401739P101 37D401739P108	—	GE Aircraft Engines (99207)	1/31/67	19	11/1/84	AR
77-11-1	SEI-154	CF700-2C/-2D/-2D-2	Exhaust Pressure Probe	5014T22G01 5014T22G02	—	GE Aircraft Engines (99207)	1/31/67	19	11/1/84	AR
77-20-0	SEI-154	CJ610-1/-4	Thermocouple Harness Assembly	37E501519P102	AA-1375-2	Atlas Aero Corp. (09526)	1/31/67	17	5/1/79	AR
77-20-1	SEI-154	CF700-2C/-2D/-2D-2	Thermocouple Harness Assembly	6012T16P03	8TE16AAM	Ametek Aerospace Products (97424)	1/31/67	17	5/1/79	AR

Technical Manual Index

CJ610 TURBOJET and CF700 TURBOFAN

Component Maintenance Manual
September 1, 2023

<u>ATA Number</u>	<u>Publ. Number</u>	<u>Engine Model</u>	<u>Nomenclature</u>	<u>Part Number</u>	<u>VIN</u>	<u>OEM Name (Vendor Code)</u>	<u>Basic Issue Date</u>	<u>Rev. No.</u>	<u>Rev. Date</u>	<u>Rev. Cycle</u>
77-20-2	SEI-154	CF700-2C/ -2D/-2D-2	Thermocouple Harness Assembly	6014T95P01	8TE16AAV	Ametek Aerospace Products (97424)	1/31/67	20	12/31/95	AR
77-30-0	SEI-154	CF700-2C/ -2D/-2D-2	Speed Sensor	3002T86P02 4011T92P01 4049T17P01	721748 721748B 724715	Electro Products Laboratories Inc. (81692)	1/31/67	16	4/1/78	AR
77-40-0	SEI-154	CJ610-9 CF700-2C/ -2D/-2D-2	Engine Temperature Protector	7022M30G01 7022M31G02 7022M31G03	—	GE Aircraft Engines (99207)	1/31/67	19	11/1/84	AR
77-40-1	SEI-154	CJ610-9	Engine Temperature Protector	4025T42P01	8TK25AAA1	Ametek Aerospace Products (97424)	1/31/67	20	12/31/95	AR
79-10-0	SEI-154	CF700-2C	Oil Tank Assembly	6002T03P04	UA526213-11	United Aircraft Products (78943)	1/31/67	11	4/1/71	AR
79-10-1	SEI-154	CJ610-1/ -5/-9 CF700-2C/ -2D/-2D-2	Oil Tank Assembly	6003T09P04	52000-153	Alloytek Inc. (55806)	1/31/67	20	12/31/95	AR
79-10-2	SEI-154	CJ610-4/ -6/-8/-8A	Oil Tank Assembly	6003T89P01 6003T89P02	52000-112 52000-113	Alloytek Inc. (55806)	1/31/67	21	5/31/98	AR

Technical Manual Index

CJ610 TURBOJET and CF700 TURBOFAN

Component Maintenance Manual September 1, 2023

<u>ATA Number</u>	<u>Publ. Number</u>	<u>Engine Model</u>	<u>Nomenclature</u>	<u>Part Number</u>	<u>VIN</u>	<u>OEM Name (Vendor Code)</u>	<u>Basic Issue Date</u>	<u>Rev. No.</u>	<u>Rev. Date</u>	<u>Rev. Cycle</u>
79-20-2	SEI-154	CJ610-1/-4/ -5/-6/-8/ -8A/-9	Lube and Scavenge Pump	37R601003P104 37R601003P112	RR16500A3 RR16500A18	Lear Siegler Inc. (51663)	1/31/67	23	8/15/00	AR
79-20-3	SEI-154	CF700-2C/ -2D/-2D-2	Lube and Scavenge Pump	37R601209P109	RR17780G	Lear Siegler Inc. (51663)	1/31/67	20	12/31/95	AR
79-21-0	SEI-154	CF700-2C/ -2D/-2D-2	Fan Scavenge Pump	4003T54P01	GD302-1	W. H. Nichols (86329)	1/31/67	21	5/31/98	AR
79-22-0	SEI-154	CJ610-1/-4 CF700-2C	Oil Filter Assembly	37C301062P103	R9W353	North American Rockwell (00736)	1/31/67	14	4/1/76	AR
79-22-1	SEI-154	CJ610-1/-4/ -5/-6 CF700-2C/ -2D/-2D-2	Oil Filter Assembly	3005T78G01	R9W818	North American Rockwell (00736)	1/31/67	14	4/1/76	AR
79-22-2	SEI-154	CJ610-1/-4/ -5/-6 CF700-2C/ -2D/-2D-2	Oil Filter Assembly	3005T78G01	54207-1	Cuno Engineering (15472)	1/31/67	14	4/1/76	AR
79-22-3	SEI-154	ALL	Oil Filter Assembly	3015T00G01	—	GE Aircraft Engines (99207)	1/31/67	9	4/1/70	AR
79-22-4	SEI-154	ALL	Oil Filter Assembly	3015T00G03	R9W1210	GE Aircraft Engines (99207)	1/31/67	13	5/1/73	AR

Technical Manual Index

CJ610 TURBOJET and CF700 TURBOFAN

Component Maintenance Manual
September 1, 2023

<u>ATA Number</u>	<u>Publ. Number</u>	<u>Engine Model</u>	<u>Nomenclature</u>	<u>Part Number</u>	<u>VIN</u>	<u>OEM Name (Vendor Code)</u>	<u>Basic Issue Date</u>	<u>Rev. No.</u>	<u>Rev. Date</u>	<u>Rev. Cycle</u>
79-22-5	SEI-154	ALL	Oil Filter Assembly	3015T00G04	54359-01	GE Aircraft Engines (99207)	1/31/67	13	5/1/73	AR
79-23-0	SEI-154	ALL	Oil Cooler Assembly	37D401061P108 37D401061P108	154410-6-1 154410-6-2	Air Research Mfg. (70210)	1/31/67	20	12/31/95	AR
79-40-0	SEI-154	CJ610-1/-4 CF700-2C	Oil Tank Relief Valve	37C301075P102	LH10420	Lourdes Industries (01178)	1/31/67	23	8/15/00	AR
79-40-1	SEI-154	ALL	Oil Tank Relief Valve	37C301075P102 37C301075P10437 C301075P105	K-1221-8-2 K-1221-8-6 K-1221-8-10	Kohler Co. (34199)	1/31/67	11	4/1/71	AR
79-40-2	SEI-154	CJ610-1/-4 CF700-2C	Oil Tank Relief Valve	37C301075P102	1112-599355	Parker Aircraft Co. (92003)	1/31/67	0	1/31/67	AR
79-43-0	SEI-154	CJ610-1	Air Leakage Check Valve	37D401330G003	—	GE Aircraft Engines (99207)	1/31/67	20	12/31/95	AR
79-43-1	SEI-154	ALL	Air Leakage Check Valve	4001T94G05 4001T94G06 4001T94G08 4001T94G09 4003T41G01	—	GE Aircraft Engines (99207)	1/31/67	20	12/31/95	AR
80-20-0	SEI-154	CJ610-1/-5/ -9 CF700-2C/ -2D/-2D-2	Ignition Exciter	37D401588P103	10-324330-3	Unison Industries (59501)	1/31/67	20	12/31/95	AR

Technical Manual Index

CJ610 TURBOJET and CF700 TURBOFAN

Component Maintenance Manual
September 1, 2023

<u>ATA Number</u>	<u>Publ. Number</u>	<u>Engine Model</u>	<u>Nomenclature</u>	<u>Part Number</u>	<u>VIN</u>	<u>OEM Name (Vendor Code)</u>	<u>Basic Issue Date</u>	<u>Rev. No.</u>	<u>Rev. Date</u>	<u>Rev. Cycle</u>
80-20-1	SEI-154	CJ610-1/-4/ -5/-6 CF700-2C	Ignition Exciter	4006T58P01 4006T58P03	42473 43249	Unison Industries (83311)	1/31/67	22	8/15/99	AR
80-20-2	SEI-154	ALL	Ignition Exciter	4026T03P01	43467K	Unison Industries (83311)	1/31/67	23	8/15/00	AR
80-21-0	SEI-154	ALL	Ignition Lead Assembly	37C311098P101 37C311098P102	59616 (Right hand) 59617 (Left hand)	Co-Operative Industries (81482)	1/31/67	22	8/15/99	AR
80-22-0	SEI-154	CJ610-1/-4/ -5/-6/-9 CF700-2C/ -2D/-2D-2	Igniter Plug	37C311124P101	FHE146-7	Champion (11583)	1/31/67	22	8/15/99	AR
80-22-0	SEI-154	ALL	Igniter Plug	37C311124P102 4013T35P01	10-360345-1 10-360947-1	Bendix Corp. (77820)	1/31/67	14	4/1/76	AR

Questions or comments concerning the content of this index should be directed to aviation.fleetsupport@ge.com.