

QUALITY REMARK: AEPD
QUALITY REQUIREMENT 231

IN ADDITION TO THE MARKING SPECIFIED BY THE DRAWING OR SPECIFICATION, MARK EACH PART WITH THE LETTER F BELOW THE DESIGNATED MARKING AREA. IF SPACE DOES NOT PERMIT, THEN MARK ADJACENT TO, BUT SEPARATE FROM, THE PART NUMBER/SERIAL NUMBER MARKING. WHERE IT IS IMPRACTICAL TO APPLY THE F WITH THE SAME MARKING METHOD, CONTACT THE PURCHASER FOR DIRECTION CONCERNING WHAT METHOD TO USE. WHERE THE PART IS TOO SMALL OR FRAGILE, MARK THE CONTAINER WITH THE LETTER F . WHEN THE PART DRAWING/SPECIFICATION REQUIRES INDIVIDUAL PACKAGE MARKING (PART NUMBER, SERIAL NUMBER, ETC.), THE PACKAGE MARKING SHALL ALSO INCLUDE THE THE LETTER F . THE SHIPPING CARTON THAT CONTAINS THESE PARTS SHALL ALSO SHOW THE LETTER F AFTER THE PART NUMBER.

USE OF GEAE APPROVED SPECIAL PROCESS SUPPLIERS IS REQUIRED FOR CLASS F HARDWARE WHEN SSE IS ON THE DRAWING. USE OF GEAE APPROVED SUPPLIERS IS NOT REQUIRED FOR SPECIAL PROCESSES ON NON-SSE PARTS. TECHNICAL PLANS AND/OR APPROVED PROCESS SHEETS AND TECHNICAL PLAN VERIFICATION IS REQUIRED WHEN IMPOSED BY GEAE SPECIFICATION(S) FOR BOTH SSE AND NON-SSE PARTS.