

QUALITY REMARK: AEPD  
QUALITY REQUIREMENT NUMBER 440  
MRB REPAIR

TYPE 1: REPAIR PROCEDURE FOR B50TF119 CLASS A,  
COMBINED WITH F50TF18 CLASS A, TOTAL REQUIREMENTS.

SUPPLIER TO SUBMIT THE FOLLOWING TO PURCHASER IN  
SHIPPING CONTAINER WITH PARTS PLUS DUPLICATE COPIES  
UNDER SEPARATE MAILING TO APPROPRIATE GE  
CONTRACT ADMINISTRATOR:

CERTIFICATE OF CONFORMANCE TO MRB REPAIR  
AND ALL APPLICABLE SPECIFICATIONS REFERENCED  
ON MRB REPAIR PROCEDURE AND PURCHASE ORDER.  
SAID CERTIFICATE SHALL INCLUDE DOCUMENTATION THAT  
PARTS WERE VISUALLY INSPECTED AND ACCEPTED BEFORE AND  
AFTER SPRAY FOR CHIPPING, FLAKING, CRACKING,  
OVERSPRAY, AND OTHER VISUAL DEFECTS.

TEST COUPONS IN ACCORDANCE WITH F50TF18 CLASS A.

DIMENSIONAL VERIFICATION OF COMPLIANCE TO COATING THICKNESS REQUIREMENTS

COPY OF MRB REPAIR PROCEDURE WITH SUPPLIER QUALITY INSPECTOR OR  
REPRESENTATIVE SIGNATURE SIGN-OFF OR STAMP ON ALL APPLICABLE ITEMS  
ON MRB REPAIR PROCEDURE INDICATING COMPLETION OF AND COMPLIANCE TO ALL  
REQUIREMENTS.